





CLARIFIER DRAIN VALVE CONTROL PANEL




PIPE GALLERY EFFLUENT PENETRATION REPAIR



2015 WATER TREATMENT PLANT
IMPROVEMENT PROJECT

TYPICAL SECTIONS & DETAILS 2



M-904